



LATITUDE	LONGITUDE	ELEVATION
N40°36.92'	W103°15.89'	4040' MSL

Navigation

VOR	GPS	ILS
114.4 (AKRON)	RWY 33	NO

Runway Data

Runway	Length	Width	Surface	Lights	VGSI	App Lgts
15/33	4708'	75'	CONC	MIRL	P2L/P2L	NONE
3/21	2500'	150'	GRVL/TURF	NONE	NONE	NONE

Communications

CTAF/UNICOM	Lights	Weather	ATIS	APP/DEP	Tower	Ground	RCO
122.8	122.8	AWOS 118.525 970-526-3009	--	118.475	--	--	--

CONTACT INFORMATION

Manager: PAT O'BRIEN
 Airport Phone: 970-522-0417
 After Hours Phone: 970-520-2325



SERVICES

Airframe: **NONE** Bottle Oxygen: **NONE**
 Power Plant: **NONE** Bulk Oxygen: **NONE**
 TSNT Storage: **HANGAR, TIEDOWN** Fuel: **100LL, JET A**
 Transportation: Courtesy car available. Hertz 970-522-7056, Halloway's Motors 970-522-0450.
 Other Services: Agricultural Spraying.

COMMUNITY


Lodging: Best Western 970-522-6265
 Comfort Inn 970-522-3700
 Super 8 Motel 970-522-0300
 Colonial Motel 970-522-3383
 Ramada 970-522-2625

Dining: Restaurants in Sterling Within 5 miles

Recreation: Overland Trail Museum 5 miles
 North Sterling Reservoir 15 miles N

REMARKS

- RWY 15 has a 425' displaced threshold.



© 2002 DeLorme (www.delorme.com) Topo USA®