



LATITUDE	LONGITUDE	ELEVATION
N40°06.25'	W102°42.78'	4136' MSL

Navigation

VOR	GPS	ILS
114.4 (AKRON)	NO	NO

Runway Data

Runway	Length	Width	Surface	Lights	VGSI	App Lgts
16/34	4200'	75'	CONC	MIRL	P2L/P2L	REIL
12/30	2900'	40'	GRVL/DIRT	NONE	NONE	NONE

Communications

CTAF/UNICOM	Lights	Weather	ATIS	APP/DEP	Tower	Ground	RCO
122.8	122.8	--	--	--	--	--	--

CONTACT INFORMATION

Manager: DOUG SANDERSON
Airport Phone: 970-848-3878
After Hours Phone: NONE



SERVICES

Airframe:	MAJOR	Bottle Oxygen:	NONE
Power Plant:	MAJOR	Bulk Oxygen:	NONE
TSNT Storage:	HANGAR, TIEDOWN	Fuel:	100LL
Transportation:	NONE		
Other Services:	Aerial Spraying		

COMMUNITY

Lodging:	Harvest Motel	970-848-5853
	Sunrise Inn	970-848-5465
Dining:	Restaurants located in Yuma	1/2 miles N
Recreation:	Indian Hills Golf Course	1 mile N

REMARKS

- RWY 12 is right traffic.
- RWY 16/34 MIRL preset dusk-dawn.
- RWY 12/30 soft when wet.
- Agricultural operations on and in vicinity of airport.



© 2002 DeLorme (www.delorme.com) Topo USA®